Job Safety Analysis

Safety Information for the University of California, Berkeley

UC Printing Services

Operation of the Challenge Drill

Task	Hazards	Controls
1. Place drill bits into spindle.	Sharp blades and drill bits.	Hold bit away from sharp edges.
2. Clearing jammed drill bit.	Sharp, spinning blades.	Clear jam in the STOP position only, or remove blade and clear jam with tool provided.
Required Training:	**Required Personal Protective Equipment (PPE)**	

Other Information:	
Contributors:	Theresa Acree, UC Printing Services.
Created:	January 2006
JSA Library Number:	UCPS-05

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150
(510) 642-3073 ● http://www.ehs.berkeley.edu