Job Safety Analysis

Safety Information for the University of California, Berkeley

UC Printing Services

Operation of the 5120 Scitey Inkjet, Kirk Rudy Base with Heater, and Kirk Rudy Tabber System

Task	Hazards	Controls
1. Set up feeder on Kirk Rudy base.	Pinch points with moving shuttle.	Set up and adjust in the STOP position only.
2. Set up heater over Kirk Rudy base.	Burns to hands.	Set up and adjust in the OFF position only.
3. Set up delivery through tabber and to delivery.	Pinch points with moving belts.	Set up and adjust in the STOP position only.

Required Training:	**Required Personal Protective Equipment (PPE)**

Other Information:	
Contributors:	Theresa Acree, UC Printing Services.
Created:	January 2006
JSA Library Number:	UCPS-10

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150
(510) 642-3073 ● http://www.ehs.berkeley.edu