

# JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

## ASUC AUXILIARY

### DROPPING OFF PAULEY BALLROOM POWER CORDS

TASK	HAZARDS	CONTROLS
1. Proceeding to location on catwalk.	Bumping head and falling.	Wear hard hats or bump caps, and appropriate footwear.
2. Dropping off the cords.	Electrocution and tripping.	Make sure that all breakers are turned off before any drops are done.
3. Moving on beams.	Falling hazard.	Use harnesses and safety lines.
4. Securing the cords.	Tripping hazard to public.	If cords are crossing foot path, use yellow cord covers. Secure the ends and middle with gaffer tape, leaving one foot of tape on both ends.
<b>Required Training:</b> Use of fall protection.	<b>Required Personal Protective Equipment (PPE)</b> Fall protection and hard hat.	

**Other Information:**

**Contributors:**

**Created:**

**JSA Library Number:**

Department: ASUC – John Rolle, Safety Coordinator  
June 2004  
ASUC-4

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150 (510) 642-3073 • <http://www.ehs.berkeley.edu>