

JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

FACILITIES SERVICES USING A 48-INCH SHEAR

TASK	HAZARDS	CONTROLS
1. Align material.	Cutting hand	Wear leather gloves. Deburr material. Do not slide hands along edges.
	Pinching hand and fingers	Keep hand and fingers from pinch point.
2. Depress foot treadle.	Pinching leg and foot	Keep leg and foot free from support arms.
	Muscle strain	Position body to maintain balance. Maximize use of legs. Avoid twisting.
	Cutting hand	Wear leather gloves. Beware of fresh, sharp edge.
Required Training: 1. Operation of foot-operated shear	Required Personal Protective Equipment (PPE) 1. Gloves	

Other Information:

Contributors:

Created:

JSA Library Number:

Senior EH&S Technician Jim Ostdick; Lead Painter Norm Strait
January 2003
FS-PAINT-18

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150 (510) 642-3073 ● <http://www.ehs.berkeley.edu>

The development of Job Safety Analyses is a Balanced Scorecard initiative of the AVC-BAS Safety Committee, sponsored by the Associate Vice Chancellor-Business and Administrative Services (AVC-BAS) and the AVC-BAS Leadership Team ● <http://bas.berkeley.edu/balancedscorecard>

