

# JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

## FACILITIES SERVICES USING A NOTCHER

TASK	HAZARDS	CONTROLS
1. Align material and lower blade.	Cutting hand	Wear leather gloves. Deburr test strips Do not slide hands along edges.
	Pinching hand	Wear gloves. Keep fingers from pinch point.
2. Pull lever to shear metal.	Cutting hand	Wear leather gloves.
	Pinching hand	Wear leather gloves. Keep fingers from pinch points.
	Muscle strain	Position body to support material, and get assistance when necessary.
3. Remove metal from notcher.	Cutting hand	Wear leather gloves. Do not slide hands along edges.
<b>Required Training:</b> 1. Learn the capacity of equipment (maximum gauge of material) 2. Training in the operation of the notcher	<b>Required Personal Protective Equipment (PPE)</b> 1. Gloves 2. Non-slip shoes	

**Other Information:**

**Contributors:**

**Created:**

**JSA Library Number:**

Senior EH&S Technician Jim Ostidick; Lead Painter, Norm Strait  
 January 2003  
 FS-PAINT-19

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150  
 (510) 642-3073 • <http://www.ehs.berkeley.edu>

