

JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

ENVIRONMENT, HEALTH & SAFETY – RADIOACTIVE WASTE STACKING MEDICAL WASTE TUBS

TASK	HAZARDS	CONTROLS
1. Preparing containers for stacking.	Spill contents.	Do not reach inside the bag. Avoid compacting.
	Stick from a sharp.	Tie the knot securely.
2. Stacking container.	Strain muscles.	Use safe body mechanics.
Required Training: Blood-Borne Pathogens Hepatitis B vaccination	Required Personal Protective Equipment (PPE): Gloves, steel toe shoes, lab coat, safety glasses	

Other Information:

Contributors:

Created:

JSA Library Number:

Environment, Health & Safety

October 2004

EHS-2HM-7

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150 (510) 642-3073 • <http://www.ehs.berkeley.edu>

The development of Job Safety Analyses is a Balanced Scorecard initiative of the AVC-BAS Safety Committee, sponsored by the Associate Vice Chancellor-Business and Administrative Services (AVC-BAS) and the AVC-BAS Leadership Team • <http://bas.berkeley.edu/balancedscorecard>