

JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

UC PRINTING SERVICES

OPERATION OF THE HANAGATA SHRINKWRAP

TASK	HAZARDS	CONTROLS
1. Place roll of shrink film onto feed carriage.	Shoulder and back injury from improper lifting over head.	Stand on platforms provided in shop.
2. Feed film as indicated by numbers through rollers.	Pricking by feeder pins.	Perform task only with stop switch engaged and feeder rollers open by lever.
3. Thread film onto film feed rollers and hot knife.	Pinch points. Hand injury.	Do not reach into rollers when engaging feed control. Do not put hands into knife area when cutting film. Remove test bag only after the knife has come to a complete stop.
4. Advance film to tie off onto waste roll.	Hand injury from heated clamp.	Do not reach into the clamp area until the knife has come to a complete stop.
Required Training:	Required Personal Protective Equipment (PPE)	

Other Information:

Contributors:

Theresa Acree, UC Printing Services.

Created:

January 2006

JSA Library Number:

UCPS-08

For more information about this JSA, contact the *Office of Environment, Health and Safety* at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150 (510) 642-3073 • <http://www.ehs.berkeley.edu>